



# Status of the MPD Support System

A.Yu. Semenov (JINR)


Thanks to S. Sukhovarov, E. Belyaeva and TSNIISM


V-th Collaboration Meeting of the MPD Experiment at the NICA Facility


April 23, 2020


# **Power Frame Requirements**

- Supports ECal, TOF and tracking systems.
- Allows re-install half-sectors.
- Total load of about 100 tons.
- Made of carbon composite.
- Max deformation less than 5 mm.












### **Power Frame Production: 25 Carbon Composite Boxes**




# **Power Frame Production: Winding of the Inner Shell**




# **Power Frame Production: Assembly of the Boxes**




# **Power Frame Production: Assembly of the Boxes**






#### **Power Frame Production: Outer Shell and Windows**



#### **Power Frame Parts**




Power frame : 1


TPC & TOF rails : 2

TOF rails : 12

Mounting brackets: 50



# **Power Frame in the MPD Magnet**



# **ECal Containers (Baskets)**


• ECal is organized into 25 sectors or 50 half-sectors.


• Each half-sector contains 48 modules.

• Fiberglass container (basket).

Total half-sector weight is about 1.5 tons.


• Max deformation is less than 0.5 mm.







### **ECal Electronics Install System**

- Replacement of electronics without calorimeter dismantle.
- SiPMs and WLS fibers match precision better than 0.5 mm.
- Heat isolation box as a support.
- 16 readout boards are located outside the box.
- 3 boxes per half-sector.







### **Baskets Production**



# **Baskets Production (Cont)**





# **Original Timeline (Contract №100-2064)**

1. Engineering Documentation: 30/04/2020

2. Baskets Production : 08/2020 → 10/2021

3. Power Frame Delivery : 01/11/2020

4. Power Frame Installation : 30/11/2020

5. Instructions & Manuals : 08/2020

### Delays should be expected!

- Only 30% of personnel work on site
- Problems with subcontractors

#### **Conclusions**

- Contractor will meet the technical requirements.
- Engineering documentation is on time (almost).
- Materials for frame and baskets production are OK.
- Unclear delays with production should be expected.
- Installation should be re-scheduled.