

## **SPD Hall**

**Livanov Alexey**

- Was done
- Is done
- Will be done



Access roads to the building are poured with concrete: September 2021





The interior painting of the walls of the hall is being completed.



Self-leveling floors have been poured. Anti-static tape has been stuck into the floor over its entire surface: 10/20/2021



Work on the technological gutters in the concrete floor has been completed: 07/08/2021



Water-type heating convectors are in the process of being connected



Image of convector. Back view.





Main entrance in Control Room



Interior decoration of the control room: 11.19.2021



The interior decoration in the main control room is almost complete.

12-01-2021 Wed 09:22:29



Camera 01

**Thanks you for you attention!**